



# The Vaccine and Infectious Disease Organization – International Vaccine Centre







# InterVac

Level 3 biocontainment  
facility built on U of S  
Campus

Provides research  
capacity for development  
and testing of vaccines  
and vaccine delivery  
systems

Constructed adjacent to  
Vaccine Infectious  
Disease Organization

145,000 sq. feet

\$145,000,000 cost







# InterVac

24/7 operation,  
regardless of  
conditions

full N+1 system  
redundancies

annual validation &  
re-certification of all  
components

regulated by Public  
Health Agency of  
Canada and Canadian  
Food Inspection  
Agency





## InterVac

Six – CL-3 independent lab modules, with each one being 1,500 sq.ft.

10 – 15 ACH in containment areas

All exhaust air to pass through single HEPA filter







## InterVac

Six – CL-3 independent lab modules, with each one being 1,500 sq.ft.

10 – 15 ACH in containment areas

All exhaust air to pass through single HEPA filter





## InterVac

Eighteen – CL-3Ag animal housing rooms, with each one being 675 sq.ft.

10 – 20 ACH in animal containment areas

All supply air to pass through single HEPA filter

All exhaust air to pass through double HEPA filter

Pressure decay tested







## InterVac

Eighteen – CL-3Ag animal housing rooms, with each one being 675 sq.ft.

10 – 20 ACH in animal containment areas

All supply air to pass through single HEPA filter

All exhaust air to pass through double HEPA filter

Pressure decay tested





# InterVac







## Mechanical - HEPA Filtration

### – High Efficiency Particulate Air Filter

- All containment exhaust air passes through 1 or 2 HEPA filters before leaving building
- Units located as close to line of containment as possible, wherever possible
- Housings stainless steel construction
- All ductwork made of welded stainless steel from line of containment to housing, tested to -10 w.c
- Filter mediums subject to annual validation (scanning)
- Use of Camfil technology



## Mechanical - HEPA Deck – Interstitial Floor above







## Mechanical – Camfil HEPA filtration

- 138 Camfil housings with a total of 255 filters





# Mechanical - HEPA Filtration – High Efficiency Particulate Air Filter








## Mechanical – HEPA filter system requirements for initial certification

- housings pressure tested with documentation
- Stainless steel ductwork pressure tested to 10” W.C.
- supply of calibration certificates for all equipment used, valid within the year
  - validation of all filters (by contractor)
  - pressure decay test of all CL-3Ag rooms, including associated ductwork and housings



## Mechanical – typical room pressure decay test







## Mechanical – HEPA filter system requirements for annual re-certification

- statement that no modification to housing occurred; if modified, housings pressure tested with documentation
- statement that no modification to stainless steel ductwork occurred; smoke test all joints; if modified pressure tested to 10" w.c.
- pressure decay test of all CL-3Ag rooms, including associated ductwork and housings
- supply of calibration certificates for all equipment used, valid within the year
- re-validation of all filters



## Mechanical – HEPA filter system growing pains

Initial filter scanning part of capital contract

- some typographical errors noted

Initial registration of filter medium before scans

- if scan unsuccessful and filter swapped out, there was no way to edit the software
- same filter serial number noted in two housings

Positional sensor issues

- incorrect initial input of scan travel distance

Scanning equipment condition upon turnover

- remediation by Camfil





## Mechanical – HEPA filter system - issues

### Probe glide gears stripped

- incorrect travel input or proximity switch failure

### Internal binding/crimping of probe hoses

- getting caught under bottom probe guide
- getting caught between probe and prox sensor
- getting caught on damper support plate
- kinked hoses establish “memory”
- insufficient space for hose to gather



## Mechanical – HEPA filter system - issues



Hoses squeezed and kinked at end of scan run





## Mechanical – HEPA filter system - issues



Hoses snagged on internal components and kinked



## Mechanical – HEPA filter system - issues



Hoses getting caught under track in triple wide filter housings






## Mechanical – HEPA filter system - issues



Installation of Heli-wrap to better gather hoses and stabilize



## Mechanical – HEPA filter system - issues



Extreme example of hoses catching on damper support place





## Mechanical – HEPA filter system - solutions

Probe glide gears stripped

- reprogrammed travel lengths
- replacement by our staff with guidance from

Camfil

Internal binding/crimping of probe hoses

- redesign of internal components and installation of hose loom
- site visit and remediation by Camfil
- longer hoses, better placement of gathers
- All accessible units refurbished; materials left for remainder



## HEPA filter system – overall thoughts

strong advocate of the system

Well suited if you have your own O&M staff  
- start scan and do other things

Camfil very supported of their product

Most problems we encountered were already  
solved in latest version of product or software



# QUESTIONS?

